

Paul M Purser • paul@purserandcompany.com

Tuesday, November 22, 2022

Architect's Field Report

5465 Interstate 55 North Frontage Rd, Jackson, MS 39206

18 November 2022 Date of Site Visit
 VGC, LLC: J William Williams & Tony Hoa Vu Contracting Company
 Clear / 56 ° F Weather / Temperature
 50% Completion Estimate
 N/A..... Schedule Conformance

Work Observed or Completed Since Last Report

Drywall Finishing & Tile Install

Present On-Site

Jason Lin (Mr. Chen's); Paul Purser (P&C)

Observations

I arrived on the job site at 1:30PM. I met Jason Lin at the grocery and he said work was continuing at a regular pace.

I entered the remodeled space of the south warehouse. Finishers were at work installing mud and finishes at drywall.

There was a single tile installer who was finishing up the large room with tile at the south wall. He has covered from the toilet area all the way around to the west rooms.

At the west warehouse, tile has been install at cleaning areas that are to be used for food preparation. Fish tanks were being prepared by workers out of plexi glass.

Paul Purser, AIA, LEED AP
Purser & Company, PA



Verifications or Requested Actions

- 1. None

Copied Recipients

Lynda Costas; Grant Monroe;

Midtown Jackson

160 McTyere Ave.
Suite B
Jackson, MS 39202

reports@purserand
company.com

601.376.9647

purserandcompany.com

Creative & Thoughtful
Architecture



Figure 1 – Property Front



Figure 2 – Interior Restaurant



Figure 3 – Interior Mudwork is ongoing



Figure 4 – Mudwork is ongoing



Figure 5 – Toilet Rooms and Mud work is ongoing



Figure 6 – Gypsum Furr down



Figure 7 – Tile install is ongoing



Figure 8 – Tile install is ongoing



Figure 9 – Tile in Toilet Rooms



Figure 10 – Tile in Toilet Rooms



Figure 11 – Tile in Toilet Rooms



Figure 12 – Tile in Toilet Rooms



Figure 13 – Tile @ rear of Restaurant Space




Figure 14 – Tile Installed at West Warehouse Cleaning